osolace osoto




Figure 1. Phase diagram for explaining the difference between analytical end industrial furfural processes.

D and D': Dew point curves

E and E': Boiling point curves

2/2




Figure 2 Schematic of the delayed decompression process for the production of furfural.




Figure 1. Phase diagram for explaining the difference between analytical and industrial furfural processes.

D and D': Dew point curves

£ and E*: Boiling point curves




Figure 2 Schemetic of the delayed decompression process for the production of furfural.